



# GENERAL WIRELESS CONCEPTS, COMMUNICATIONS & SCALE ACCESSORIES

## AL-03 Tower Display




## HF-AD-DA Wireless Box (Load cell to indicator)



### APPLICATIONS

- **Accuracy:** 1/10,000 for any indicator
- **Load cell:** 1 to 12 load cells 350Ω
- **Frequency bands:** 433MH z
- **Working temperature:** -10C to +60C
- **Power consumption:** 270 hours under weighing mode for one load cell 350Ω
- 29 months under sleeping mode (battery should be recharged every 5 months)

## HF-W wireless RS232 box (indicator to remote display or PC)



### APPLICATIONS

- One pair of wireless box: one for transfer and one for receiver
- Can be used for any indicator to any remote display with RS232 communication
- Baud rate can be chosen before deliver (according to the indicator and display)
- 5-9V you can be supplied from outer or supplied by indicator PC

## RS232 to RS485 converter



## RS232 serial to USB converter



## Blue-tooth communication for BW indicator -short distance



BLUETOOTH - 100M

**SHEKEL PC  
Software**

**TSCALE PC  
Software**

**GENERAL  
indicator to  
PC Software**

