



# Model OCS-S1

## General Purpose digital Hanging scale

### Functions:

- ◆ Zero
- ◆ Tare
- ◆ Hold
- ◆ Auto power-off
- ◆ Battery supervision
- ◆ Overload alarm
- ◆ Unit switch

### Specification:

- ◆ Accuracy class OIML III
- ◆ Tare range 100%F.S.
- ◆ Zero range 4%F.S.
- ◆ Safe overload 120%F.S.
- ◆ Overload alarm 100%F.S.+9e
- ◆ Battery AA\*4
- ◆ Battery life >100h
- ◆ Temperature range -10°C~40°C



### Features:

- ◆ Aluminum die-casting case
- ◆ Stainless steel shackle
- ◆ Alloy steel hook
- ◆ LED module display
- ◆ AA x 4 batteries
- ◆ Remote
- ◆ **Capacity:** 500kg x 200g  
1000kg x 500g

